

Limit Resistor

Auto Reset  
Breaker

Converter  
Negative

Charger  
Output

SCR

POWER  
TRANSFORMER

PCB

12 VDC HEATSINK

Unfiltered  
Converter  
Output

LINE FUSE

TRANSFER RELAYS

LINE HOT

LINE NEUTRAL

